

March 28, 2007

Racine Harbor Commission

From: Alan Veenstra

RE: Mooring proximity

I have had a continuous mooring assignment at C-2 in Racine Harbor for more than 12 years. In that time my placement has remained unchanged. In fact, the mooring is screwed into the bottom and cannot be moved easily.

Last season a new mooring assignment was placed at B-2 (or B-3), a placement that is dangerously close to my vessel during Easterly winds. I spoke with Mark Lovdahl about this issue last Fall and he suggested that your office must handle this issue. Given that less than 10' separates our vessels at times, I believe it is prudent to either adjust the location of that other mooring or move it to any of the many open areas in the harbor.

Thanks for your kind attention. I look forward to your prompt action.

Sincerely,

773 791 7923 cell

alan@chicagosailing.com