

June 10, 2024

Ron J. Pritzlaff, P.E. Assistant Commissioner of Public Works/Operations 730 Washington Ave., Room 304 Racine, WI 53403 Ronald.pritzlaff@cityofracine.org

RE: Racine Tuckpointing Additional Work Items

Dear Mr. Pritzlaff.

Berglund Construction proposes to furnish all labor, material, and equipment to perform the following scope of work as outlined below. Pricing us based upon your email dated April 26, 2024.

Scope of Work:

- Item #3: Memorial Hall Restoration of exterior "Golden Oak" doors on west elevation.
- Item #4: Memorial Hall 100% tuckpointing of North Brick Wall and replacement of sealant joints around wall penetrations.
- Item #5: Memorial Hall Dutchman repair in two (2) locations on the tone steps on the south side of the building.
- Item #8: City Hall Annex Repointing and sealant repairs on the rest of the west elevation (not already in the original scope of work).
 - 100% repointing of all mortar joints
 - Replacement of all sealant joints within elevation
 - Replacement of sealant/mortar joints within limestone coping at parapet wall with new sealant joints, in lieu of mortar, including inside joints and across counter flashing on inside of parapet wall
 - o Demo and remove old unused wing-walls that protrude out from the main elevation

Lump Sum Cost: \$261,802.23

Sincerely,

John McHugh

Vice President - Restoration

A. Potential Additional Work Items

 Memorial Hall - Full restoration of wood windows on 1st floor of Memorial hall, on East and North elevations.



2. **Memorial Hall** – Replacement of Kalwall windows on south elevation




3. **Memorial Hall - R**estoration of exterior of "Golden Oak" doors on west elevation.



Memorial Hall – 100% tuckpointing of North Brick Wall (and replacement of sealant joints around wall penetrations)



5. Memorial Hall – Dutchman repair in 2 locations on the stone steps on the south side of the building.



6. Memorial Hall – Route and seal the rest of the cracks in the concrete 1st floor wall (below the few that are already getting repaired above the doors), including the north elevation.



- 7.
- City Hall Annex Repointing and sealant repairs on South Elevation
 a. 100% repointing of all mortar joints
 b. Replacement of all sealant joints within elevation.
 c. Replacement of sealant/mortar joints within limestone coping at parapet wall with new sealant joints, in lieu of mortar, including inside joints and across counter flashing on inside of parapet wall.












Whole south elevation



- 8. **City Hall Annex** Repointing and sealant repairs on the rest of the west elevation (what's not already in the original scope of work)
 - a. 100% repointing of all mortar joints
 - b. Replacement of all sealant joints within elevation.
 - c. Replacement of sealant/mortar joints within limestone coping at parapet wall with new sealant joints, in lieu of mortar, including inside joints and across counter flashing on inside of parapet wall.
 - d. Demo and remove old unused wing-walls that protrude out from the main elevation (bottom 2 photos below)













