


# 5110 Washington Avenue

Note that photos taken AFTER Racine Co. Sheriff's investigation.



Exterior door



Exterior door



Smashed exterior door



Laundry- no system to determine if clean or soiled



Bathroom/chemical storage



Bathroom



Bathroom



Bathroom




Bathroom- hole in wall, suspected plumbing leak



Storage closet/water heater room



Unshielded lights in hallway



Water damage in bathroom & missing base cove



Water damage in bathroom & missing base cove



Caulk in disrepair at bathroom sink



Water damage bathroom




Bathroom- soiled wall, missing door threshold, base coving in disrepair




Kitchen room



Kitchen Room



Rice actively cooking in rice steamer



Kitchen room



Electrical box above kitchen prep space with note stating, "Everything has to be at least 3 feet away from electrical box"



Kitchen room- Microwave and food stored under the electrical box



Kitchen room




Kitchen room



Kitchen room



Kitchen room



Dresser in hallway adjacent to laundry basket, drawer contains massage stones




Dresser in hallway adjacent to laundry basket




Dresser in hallway adjacent to laundry basket



Dresser in hallway adjacent to laundry basket- Interior of incubator (warm and functioning)



Dresser in hallway adjacent to laundry basket - Unlabeled liquids on top of dresser adjacent to massage stones



Dresser in hallway adjacent to laundry basket



Laundry basket



Water damaged ceiling tiles




Massage Room C




Massage Room C




Massage Room C



Massage Room C



Massage Room C



Massage Room C



Massage Room C



Massage Room B



Massage Room B



Massage Room B



Massage Room B



Massage Room B



Massage Room B



Massage Room B



Mini fridge in hallway outside of massage rooms- Interior refrigerator



Mini fridge in hallway outside of massage rooms- Interior refrigerator



Mini fridge in hallway outside of massage rooms- interior freezer



Mini fridge in hallway outside of massage rooms- Interior freezer



Massage Room A



Massage Room A



Massage Room A



Massage Room A




Massage Room A




Massage Room A



Massage Room A



Massage Room A



Massage Room A



Massage Room A



Massage Room A

# **RELAX SPA MASSAGE**

(262) 865 - 3329



## **BODY MASSAGE**

(Deep Tissue & Hot Stone - \$10)  
(Essential Oil - \$10, CBD Oil - \$20)

**30 Minutes - \$55**  
**60 Minutes - \$75**  
**90 Minutes - \$110**  
**120 Minutes - \$140**

## **FOOT MASSAGE**

(Deep Tissue & Hot Stone - \$10)  
(Essential Oil - \$10, CBD Oil - \$20)

**30 Minutes - \$55**  
**60 Minutes - \$75**  
**90 Minutes - \$110**  
**120 Minutes - \$140**

## **COUPLE**

(Deep Tissue & Hot Stone - \$10 each)  
(Essential Oil - \$10 each, CBD Oil - \$15 each)

**30 Minutes - \$110**  
**60 Minutes - \$140**  
**90 Minutes - \$210**  
**120 Minutes - \$270**

## **FOUR HAND BODY MASSAGE**


(Deep Tissue & Hot Stone - \$20)  
(Essential Oil - \$10, CBD Oil - \$20)

**30 Minutes - \$110**  
**60 Minutes - \$140**  
**90 Minutes - \$210**  
**120 Minutes - \$270**

Posted services offered



Department of Safety and Professional Services (DSPS) Massage Therapist license



City of Racine License for Massage Establishment